



BlackBerry 7510 Vibration Motor Replacement

Written By: Neil Johnson



INTRODUCTION

This will show you how to repair the vibrating motor in your blackberry.



TOOLS:

- [T6 Torx Screwdriver](#) (1)
-

Step 1 — Back Face of Phone



❗ Remove the battery cover and battery before continuing.

- Remove the six T6 screws.

Step 2



- Pry open the back cover.

Step 3





- Lift off the back cover.

Step 4



- Remove the two T6 screws.

Step 5



- Remove the daughterboard.
- Remove the exposed vibration motor.

Step 6 — Vibration Motor



- Replace with new vibration motor

To reassemble your device, follow these instructions in reverse order.

